



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20UNS

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	27/07/2020	VIN	W1V9076352P250428	CAP Average	£3,075.00
Year	2020	Body Style	Panel Van L3	CAP Below	£2,500.00
Mileage	331,842 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	26/07/2026	Gears	6
Colour	WHITE	CAP Clean	£3,600.00		

AD-BLUE, SIDE LOADING DOOR



Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing nsf
Dented
Over 30mm

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Sill ns
Dented
Over 30mm

6: Sill ns
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint

10: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



11: Sill os
 Dented
 Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK