

VEHICLE INSPECTION REPORT

PF14TZB

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/08/2014

Colour RED

Cab Type DAY CAB

Year 2014

VIN XLRAEL1500L437978

Gearbox MANUAL

Mileage 456,525 Km Warranted

Body Style Box Van

Axle Combi 4x2

Fuel Type DIESEL

Service history Yes

Rear Suspension Spring

GVW 7500kg

MOT Due 31/03/2027

Tail Lift Cantilever

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1


OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
UpTo 25mm Thru Paint

4: Screen Front
Chipped
Over 10mm



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Fog Lamp Surround ns
Broken
Replace



7: Bumper Front
Scratched
25 to 100mm Thru Paint

8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

10: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Bumper Rear
Rusted
Over 5mm

14: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
Edge Chip

18: Centre Console Front
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		